

WVU ENVIRONMENTAL HEALTH AND SAFETY DINING HALL AUDIT REPORT

| DINING HALL LOCATION: | NUMBER OF VIOLATIONS: | |
|--|--|------|
| Summit Café | Priority: | 0 |
| INSPECTION TYPE: | Priority Foundation: | 0 |
| Routine | | |
| DATE OF INSPECTION: | Core: | 1 |
| 2/10/23 | Total: | 1 |
| | | |
| VIOLATION #1 | | |
| Criticality: Core | Corrected During Visit? Yes | No 🗸 |
| OBSERVATION: | | |
| 5-205.15 - SYSTEM MAINTAINED IN GOOD REPAIR - Spr drainboards. | ay nozzles extending to low and are resting on the | |
| CORRECTION NEEDED: | | |
| Spray nozzles in the warewashing areas need to be adjuste | d so they hang above the flood rims of the sinks. | |
| | | |
| VIOLATION #2 | | |
| Criticality: | Corrected During Visit? Yes | No O |
| OBSERVATION: | | |
| | | |
| CORRECTION NEEDED: | | |
| | | |