

# WVU ENVIRONMENTAL HEALTH AND SAFETY DINING HALL AUDIT REPORT

## DINING HALL LOCATION:

Café Evansdale

## INSPECTION TYPE:

Routine

## DATE OF INSPECTION:

3/28/23

## NUMBER OF VIOLATIONS:

Priority:	1
Priority Foundation:	0
Core:	1
Total:	2

## VIOLATION #1

Criticality: Priority

Corrected During Visit? Yes  No

### OBSERVATION:

5-203.14 - BACK FLOW PREVENTION DEVICE - The side kick valve was removed from the mop sink and the chemical dispensing unit was connected with the water on. This is a back-flow issue.

### CORRECTION NEEDED:

The side kick valve needs to be placed back into service on the mop sink and remain in place. The on/off shut off knobs need to be put back on the faucet.

## VIOLATION #2

Criticality: Core

Corrected During Visit? Yes  No

### OBSERVATION:

5-205.15 - SYSTEM MAINTAINED IN GOOD REPAIR - Several hand sinks and a prep sink had water dripping from the faucets.

### CORRECTION NEEDED:

Repair the shut off valves and/or "O" rings of the sinks to stop the water dripping.