

WVU ENVIRONMENTAL HEALTH AND SAFETY DINING HALL AUDIT REPORT

DINING HALL LOCATION:

Summit Café

INSPECTION TYPE:

Routine

DATE OF INSPECTION:

4/6/22

NUMBER OF VIOLATIONS:

Priority:	0
Priority Foundation:	0
Core:	1
Total:	1

VIOLATION #1

Criticality: Core

Corrected During Visit? Yes No

OBSERVATION:

5-205.15- SYSTEM MAINTAINED IN GOOD REPAIR- Water dripping from the hot water handle of the produce sink.

CORRECTION NEEDED:

Place a work order to have the hot water handle/valve repaired to stop it from dripping water when shut off.

VIOLATION #2

Criticality:

Corrected During Visit? Yes No

OBSERVATION:

CORRECTION NEEDED: